

19 Legare St

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
J. T. Dell, dwelling	Brick	Slate	40	20	40	Repaired	repaired	repaired	repaired	repaired	n/g

What should be done to make it safe	Remarks
"O.K."	