

Photo #	Wragg Address	Level (if applicable)	Description	Note
Aug13 2012 2 wragg.007	2		Stair riser, w/ uncovered original paint	
Aug13 2012 2 wragg.008	2		Stair riser, w/ uncovered original paint	
Aug13 2012 2 wragg.024	2		Plaster work, Ground level, SW room	
Aug13 2012 2 wragg.025	2		SW room, First level, window trim (View of 4 Wragg)	
Aug13 2012 2 wragg.027	2		Parlor door hardware	
Aug13 2012 2 wragg.035	2		Detail of piazza colum	
WraggExterior.002	2		French door w/ transom off piazza, fac. South	
WraggExterior.004	2		Ballusters on piazza	Match to William Aiken's Number 10 Green Street property, now owned by CofC
WraggExterior.020	2		South elevation	
WraggExterior.021	2		South elevation from interior of Mall	
WraggExterior.026			Wragg Mall, fac. West	
WraggExterior.030			Wragg Mall, fac. West	
WraggExterior.034			2 Wragg/ARH from head of Wragg Mall	
WraggExterior.038	2		South Elevation	
WraggExterior.040	2		South Elevation	
WraggExterior.041	2		South Elevation	
WraggExterior.042	2		Piazza foundation, fac. South	
WraggExterior.043	2		Lower piazza, ballusters, facing South	
WraggExterior.049	2		East elevation	
WraggExterior.050	2		East elevation	
WraggExterior.052			View of 2 Wragg from ARH front door	
WraggExterior.057	2		View of upper piazza, ornamental features	
WraggExterior.058	2		View of front door, piazza	
WraggExterior.059	2		Iron gate on western easement, fac. South	
WraggExterior.060	2		Western easement between 4 and 2 Wragg (l-r)	
WraggExterior.061	4		East elevation	
WraggExterior.062	2		Lower piazza, facing East	
WraggExterior.063	2		Western easement	
WraggExterior.076	2		View of North elevation from garden	
WraggExterior.077	2		View of North elevation from garden	
WraggExterior.078	2		window, ext. door SE half, North elevation	
WraggExterior.079	2		Remnant earthquake damage over NE first level window	
WraggExterior.080	2		Remnant earthquake damage over ext. door on SE half of North elevation, ground level	
WraggExterior.081	2		Cistern in garden	
WraggExterior.082	2		Addition, fac. South	
WraggExterior.084	2		Modern woodshed, NW corner of property	
WraggExterior.085	2		Original wall (in ivy) with additional wall attached (curved) around tree at North of property	
WraggExterior.089	2		Brick-lined path, east easement, fac. North (w/ pvc visible)	

Photo #	Wragg Address	Level (if applicable)	Description	Note
WraggExterior.090	2		Brick-lined path, east easement, fac. North	
WraggExterior.092	2		East easement of property, fac. South	
WraggExterior.093	2		2 Wragg garden, fac. NW	
WraggExterior.094	2		North side of addition to house (c. 1990s), fac. West	
WraggExterior.095	2		Early brick-lined pathway associated w/ eastern easement of property	Archaeological in nature; was discovered by current owner while gardening
WraggExterior.096	2		Early brick-lined pathway associated w/ eastern easement of property	Archaeological in nature; was discovered by current owner while gardening
WraggExterior.098	2		2 Wragg, east easement, fac. North	
WraggExterior.100			Aiken-Rhett House (ARH), view from 2 Wragg	
WraggExterior.101	2		2 Wragg, lower piazza	
WraggExterior.102	4		4 Wragg, drive, fac. North	
WraggExterior.104	4		4 Wragg, fac. North	
WraggExterior.105			Wragg St., fac. East	
WraggExterior.109			Wragg St., fac. West	
WraggExterior.110	4		4 Wragg, West elevation	
WraggExterior.111	4		4 Wragg, West elevation	
WraggExterior.112	4		4 Wragg, West elevation	
WraggExterior.113	4		4 Wragg, West elevation	
WraggExterior.114	4		4 Wragg, West elevation	
WraggExterior.115	4		4 Wragg, West elevation	
WraggExterior.117			CPA construction area, former row, fac. West	
WraggExterior.122			Wragg Mall, fac. E/SE (Museum in background)	
WraggExterior.124			CPA from Mall, former location portion of row, fac. North	
WraggExterior.125			CPA from Mall, former location portion of row, fac. North	
WraggExterior.127	4		4 Wragg, CPA in fore, fac. E/NE	
WraggExterior.128	4		4 Wragg, Charleston Progressive Academy (CPA) in fore, fac. E/NE	
WraggExterior.129			Wragg Mall, Fac. East	
WraggExterior.130	4		4 Wragg, fac. NE	
WraggInterior.003	2	Attic	View	
WraggInterior.004	2	Attic	View	
WraggInterior.005	2	Attic	View	
WraggInterior.018	2	First	Flemish bonded brick detail between windows on piazza	
WraggInterior.022	2	First	View of 4 Wragg from central point on piazza	
WraggInterior.023	2	First	View of 4 Wragg from piazza	
WraggInterior.029	2	First	View of ARH from piazza	
WraggInterior.030	2	First	View of carriage house at ARH from piazza	
WraggInterior.031	2	First	Piazza, fac. West	
WraggInterior.032	2	First	Piazza, fac. West	
WraggInterior.034	2	First	View of Wragg Mall from piazza	

Photo #	Wragg Address	Level (if applicable)	Description	Note
WraggInterior.035	2	First	Wragg Street view from piazza	
WraggInterior.036	2	First	Piazza ceiling	
WraggInterior.041	2	First	Exterior door trim, piazza	
WraggInterior.042	2	First	Exterior door trim, piazza, fac. North	
WraggInterior.043	2	First	Exterior door, piazza, fac. North	
WraggInterior.045	2	First	Hall, fac. North	
WraggInterior.047	2	First	SE room trim	
WraggInterior.048	2	First	SE room, fac. North	
WraggInterior.049	2	First	View of central window, fac. North	
WraggInterior.054	2	First	SW room, fac. West	
WraggInterior.056	2	First	SW room, fac. North	
WraggInterior.067	2	First	SW room, fac. East	
WraggInterior.070	2	First	SW room, fac. West	
WraggInterior.083	2	First	SE room, fac. SE	
WraggInterior.086	2	First	Original plaster and lathe, SE Room (NE corner)	
WraggInterior.092	2	First	View of Aiken-Rhett House (ARH) from SE room, fac. East	
WraggInterior.093	2	First	SE room, fac. North	
WraggInterior.099	2	First	Door onto piazza	
WraggInterior.100	2	First	NE room, fac. East	
WraggInterior.101	2	First	Attic access, NE room	
WraggInterior.103	2	First	NE room, fac. North	
WraggInterior.108	2	First	NW room, fac. East	
WraggInterior.110	2	First	NW room, fac. East	
WraggInterior.111	2	First	NW room, mantle detail, original paint (black tint)	
WraggInterior.116	2	First	NW room	
WraggInterior.122	2	First	Pine floor	
WraggInterior.123	2	First	Pine floor	
WraggInterior.124	2	First	Door jamb of first floor NW room, exposing some original paint	
WraggInterior.126	2	First	View of stairs toward central window	
WraggInterior.127	2	First	View of stairs toward central window	
WraggInterior.131	2	First	Central window, palmette trim	
WraggInterior.139	2	First	Sill, detail central window	
WraggInterior.140	2	First	View of central window from first floor, fac. North	
WraggInterior.143	2	First	Trimwork on stairs	
WraggInterior.148	2	First	View from central window on stair onto roof of addition, fac. North	
WraggInterior.149	2	First	View of 1st floor from stair	
WraggInterior.154	2	Ground	Parlor doors between SW/NW rooms (Parlor/Dining room)	
WraggInterior.158	2	Ground	SW room, fac. S/SW	

Photo #	Wragg Address	Level (if applicable)	Description	Note
WraggInterior.159	2	Ground	SW room, fac. S/SW	
WraggInterior.162	2	Ground	SW room, mantle/hearth	
WraggInterior.164	2	Ground	SW room, window trim, west end	
WraggInterior.165	2	Ground	SW room, facing southeast	
WraggInterior.169	2	Ground	SE room, facing north	
WraggInterior.170	2	Ground	SE room, facing north	
WraggInterior.171	2	Ground	SE room, facing hallway (west)	
WraggInterior.172	2	Ground	SE room, south transom-french door	
WraggInterior.181	2	Ground	Inerior view of original access under stairway	
WraggInterior.182	2	Ground	View from original exterior door to addition	
WraggInterior.185	2	Ground	View from addition to original exterior door, detail	
WraggInterior.187	2	Ground	View from addition to original exterior door, which acceses under stairs. This was a servant's entrance from detached kitchen	
WraggInterior.188	2	Ground	Pine floor w/ hatch access for beneath the house	
WraggInterior.189	2	Ground	Stairway trimwork	
WraggInterior.190	2	Ground	Newell post detail, stairway	
WraggInterior.191	2	Ground	Newell post detail, stairway	
WraggInterior.192	2	Ground	Newell post detail, stairway	
WraggInterior.194	2	Ground	Trimwork SW room	
WraggInterior.196	2	Ground	NW room, fac. North w/ mantle, hearth	
WraggInterior.198	2	Ground	NW room, fac. North	
WraggInterior.199	2	Ground	Trimwork. NW room, adjacent to addition	
WraggInterior.200	2	Ground	Dining Room. Door/window formerly part of exterior before twentieth century additions	
WraggInterior.202	2	Ground	Parlor/Dining Room (SW, NW rooms)	
6May2012.002	2	Attic	View of hipped roof construction	
6May2012.007	2	Attic	View of hipped roof construction	
6May2012.008	2	Attic	View of hipped roof construction	
6May2012.009	2	Attic	View of hipped roof construction	
6May2012.011	2	Attic	View of hipped roof construction	
6May2012.013	2	Attic	View of hipped roof construction	
6May2012.014	2	Attic	Detail of house construction, wrought nails in situ	
6May2012.015	2	Attic	Detail of house construction, wrought nails in situ	
6May2012.021	2		View of cistern interior	
6May2012.022	2		View of cistern interior	
6May2012.025	2		View of cistern interior	
6May2012.027	2		View of aboveground brick structure over original cistern, fac. South	
6May2012.029	2		View of aboveground brick structure over original cistern, fac. South	

Photo #	Wragg Address	Level (if applicable)	Description	Note
6May2012.033	2		View of cistern interior **	Modern built-up well feature can be differentiated from original cistern by difference in mortar; 1990s structure has mortar while original cistern is mortar bare below.
6May2012.037	2		View of cistern interior	
6May2012.041	2		View of cistern interior	
6May2012.049	2		View of wall along stairway w/ exposed original plasterwork/paint (detail)	
6May2012.050	2		View of wall along stairway w/ exposed original plasterwork/paint (detail)	
6May2012.051	2		View of wall along stairway w/ exposed original plasterwork/paint (detail)	
6May2012.052	2		View of wall along stairway w/ exposed original plasterwork/paint (detail)	
6May2012.053	2		View of wall along stairway w/ exposed original plasterwork/paint (detail)	
6May2012.054	2		View of wall along stairway w/ exposed original plasterwork/paint	
6May2012.055	2		View of evidence of early 20th c. addition above exterior central window on North elevation (detail)	
6May2012.056	2		View of evidence of early 20th c. addition above exterior central window on North elevation (detail)	
6May2012.057	2		View of evidence of early 20th c. addition above exterior central window on North elevation	
6May2012.058	2		View of cistern location in center of yard, north half of property *	Exposed aboveground brick resembling a well structure built in 1990s; Original cistern flush w/ ground surface.
6May2012.061	2		View of North elevation with modern addition roof and view of evidence of early 20th century addition above ext. central window	
6May2012.065	2		View of upper NE corner of house, fac. East	
6May2012.066	2		View of NE corner of house from addition roof, fac. East	
6May2012.067	2		View of property garden (east end) w/ Elizabeth Street in background, fac. N/NE from addition roof	
6May2012.068	2		View of property garden (east end) w/ Elizabeth Street in background, fac. N/NE from addition roof	
6May2012.076	2		View of foundation beneath house	
6May2012.081	2		View of foundation beneath house	
6May2012.091	2		View of foundation beneath house	
6May2012.101	2	First	Exposed original paint on stair riser at First level	
6May2012.102	2	First	Exposed original paint on stair riser at First level	
6May2012.103	2	First	Exposed original paint on stair riser at First level	
6May2012.104	2	First	Exposed original paint on stair riser at First level	

Photo #	Wragg Address	Level (if applicable)	Description	Note
6May2012.109	2		View of trim, SW room on ground level	
6May2012.118	4		View of piazza foundation (original except for floor covering)	
6May2012.119	4		View of piazza foundation (original except for floor covering)	
6May2012.123	2		Brick-lined pathway on east easement	
6May2012.127	2		20th century addition off of south elevation	
6May2012.128	2		Vent, South elevation on south end	
6May2012.134	2		Front door door knock	