

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
First National Bank Telegraph Office	Brick	Slate	50	25	25	Good	Bad & cracked on east corner	Good	Must come down	Tops off; chimneys must be repaired between floors	\$1675	West wall rebuilt and chimneys repaired before fires are built	[none]

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives