

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11.28.89

Video: Reel/Frame

Survey Team: SOB
Members:

Camera:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: 43 Church

Tax Map Number: 457-16-4-20

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☒ 1 ☐ 2 ☒ 3 ☐ 4 ☐

Attic or Half Story ☒

Material:

Structure: Brick ☒ Wood Frame ☐ Stone ☐ Metal ☐
Other ☐:

Surface Covering: Stucco ☐ Wood Siding ☒ Other ☐:

Roof Covering: Slate ☒ Metal ☐ Tile ☐ Asphalt ☐
Other ☐:

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☐:

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☒ Stone ☐ Other ☐

Comments:

H₂O damage - foundation - flood area
chipped paint
Shutter loss
Slate loss on roof

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement

[]

[]

[]

1st Floor

[]

[]

[]

2nd Floor

[]

[]

[]

3rd Floor

[]

[]

[]

4th Floor

[]

[]

[]

Attic

[]

[]

[]

Doors

☒

[]

[]

Windows

☒

[]

[]

Shutters

X

15%

Piazza/Portico

☒

[]

[]

Downspouts

☒

[]

[]

Gutters

☒

[]

[]

Cornice

☒

[]

[]

Parapet

☒

[]

[]

Roof Covering

[]

[]

☒

30% (+)

Dormers (Number: 2)

☒

[]

[]

Chimneys (Number: 2)

☒

[]

[]

Other Visible Damage

Garden Walls/Fences

☒

[]

[]

Gates

☒

[]

[]

Walkways/Paving

☒

[]

[]

Sidewalks

☒

[]

[]

Trees

☒

[]

[]

Mechanical

[]

[]

[]

