

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 7 AUGUST 1990

Video: Reel/Frame

Camera:

Slides: [/] 35mm

B. & W.: [/]

Survey Team:

Members: LM/NR/CL

Name of Property: (if any)

Street Address: 73 CANNON

Tax Map Number: 460-12-1-3

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☐ 3 ☒ 4 ☐

Attic or Half Story ☒

Material:

Structure: Brick ☒ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐

Surface Covering: Stucco ☐ Wood Siding ☒ Other ☐

Roof Covering: Slate ☒ Metal ☐ Tile ☐ Asphalt ☐
Other ☐

Piazza: Foundation: Brick ☐ Stone ☐ Wood ☐
Other ☐

N/A Main Piazza: Brick ☐ Wood ☐ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☒ Stone ☐ Other ☐

Comments: ROOF CURRENTLY BEING REPLACED

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

\$

Exterior Features

Walls: Foundation/Basement

☒☐☐

1st Floor

☒☐☐

2nd Floor

☒☐☐

3rd Floor

☐☒☐

4th Floor

☐☐☐

Attic

☐☒☐

Doors

☒☐☐

Windows

☒☐☐

Shutters

Piazza/Portico

☐☐☐

Downspouts

☒☐☐

Gutters

☒☐☐

Cornice

☒☐☐

Parapet

☒☐☐

Roof Covering

☐☐☒

Dormers (Number: 3)

☐☒☐

Chimneys (Number: 2)

☐☒☐

Other Visible Damage

Garden Walls/Fences

☐☐☐

Gates

☐☐☐

Walkways/Paving

☐☐☐

Sidewalks

☐☐☐

Trees

☐☐☐

Mechanical

☐☐☐