

HISTORIC CHARLESTON FOUNDATION  
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/17/89

Job #2  
Survey Team: HODGES  
Members: SAYER, MARCH,  
REYNOLDS

Video: Reel/Frame

Camera:

Slides: [2-26]

B. & W.: [444]

Name of Property: (if any)

Street Address: 17 Meeting St

Tax Map Number: 457-16-2-44

Current Owner:

DESCRIPTION

Principal Building  Dependency [ ] Other [ ]

No. of Stories: Basement [ ] 1 [ ] 2 [ ] 3  4 [ ]

Attic or Half Story [ ]

Material:

Structure: Brick  Wood Frame [ ] Stone [ ] Metal [ ]  
Other [ ]:

Surface Covering: Stucco  Wood Siding [ ] Other [ ]:

Roof Covering: Slate [ ] Metal  Tile [ ] Asphalt [ ]  
Other [ ]:

Piazza: Foundation: Brick  Stone [ ] Wood [ ]  
Other [ ]:

Main Piazza: Brick [ ] Wood  Other [ ]

Roof Covering (if different from main building):

Chimneys: Brick  (2) Brick & Stucco [ ] Stone [ ] Other [ ] (13)  
ceramic

Comments:

metal cornices  
detached at building

## Damage Assessment

None

Minor

Major

%

## Exterior Features

Walls: Foundation/Basement   1st Floor   2nd Floor   3rd Floor   4th Floor   Attic   Doors   Windows   glass broken  
panes

## Shutters

Piazza/Portico   Downspouts   Gutters   Cornice   Parapet   Roof Covering   Dormers (Number: 0)   Chimneys (Number: 5)   

## Other Visible Damage

Garden Walls/Fences   Gates   Walkways/Paving   Sidewalks   Trees   Mechanical   detached  
out building

