

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/16/89

Video: Reel/Frame

Camera:

Slides: [I.3-4]

B. & W.: [I-9-11]

Survey Team: S.O.B #2

Members:

Hudgins, March
Reynolds, Taylor

Name of Property: (if any)

Street Address: 4 Atlantic

Tax Map Number: 457-10-4-73

Current Owner:

DESCRIPTION

Principal Building Dependency Other

No. of Stories: Basement 1 2 3 4

Attic or Half Story

Material:

Structure: Brick Wood Frame Stone Metal
Other :

Surface Covering: Stucco Wood Siding Other :

Roof Covering: Slate Metal Tile Asphalt
Other :

Piazza: Foundation: Brick Stone Wood
Other :

Main Piazza: Brick Wood Other

Roof Covering (if different from main building):

Chimneys: Brick Brick & Stucco Stone Other

Comments:

Address: 4 Atlantic Tax Map No.: 457-16-4-73 Page 2

Damage Assessment None Minor Major %

Exterior Features

Walls: Foundation/Basement	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
1st Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2nd Floor	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3rd Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4th Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Attic	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Doors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Shutters	<input checked="" type="checkbox"/>		
Piazza/Portico	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Downspouts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gutters	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> 5%
Cornice	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Parapet	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Roof Covering	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Dormers (Number: 0)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Chimneys (Number: 2)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Other Visible Damage

Garden Walls/Fences	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gates	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Walkways/Paving	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sidewalks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Trees	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/> 15%
Mechanical	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

