

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
R. Lewis, dwelling	Frame	Tin	45	18	25	Frame	Good	Good		Good	[none]

What should be done to make it safe	Remarks
"O.K."	[none]

4 Water St.