

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 7/2/90

Video: Reel/Frame

Camera:

Slides: [2]

B. & W.: [2]

Survey Team:

Members: Lund, McCallum,
Rowe

Name of Property: (if any)

Street Address: 43 Eliz. St.

Tax Map Number: 459-13-1 lot 33

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐
Attic or Half Story ☒

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐:

Surface Covering: Stucco ☐ Wood Siding ☒ Other ☐:

Roof Covering: Slate ☐ Metal ☒ Tile ☐ Asphalt ☐
Other ☒: wood shingles w/ metal over it

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☐:

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☐ Stone ☐ Other ☐
N/A

Comments:

very damaged

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

\$

Exterior Features

Walls: Foundation/Basement

[]

[✓]

[]

1st Floor

[]

[✓]

[]

2nd Floor

[]

[✓]

[]

3rd Floor

[]

[]

[]

4th Floor

[]

[]

[]

Attic

[]

[]

[✓]

Doors

[✓]

[]

[]

Windows

[]

[✓]

[]

Shutters

same damage

Piazza/Portico

[]

[]

[✓] roofing

Downspouts

[]

[]

[✓]

Gutters

[]

[]

[✓]

Cornice

N/A

[]

[]

[]

Parapet

N/A

[]

[]

[]

Roof Covering

[]

[]

[✓] gone 100%

Dormers (Number: N/A)

[]

[]

[]

Chimneys (Number: N/A)

[]

[]

[]

Other Visible Damage

Garden Walls/Fences

[✓]

[]

[]

Gates

[]

[✓]

[]

Walkways/Paving

[✓]

[]

[]

Sidewalks

[✓]

[]

[]

Trees

[]

[]

[X] back

Mechanical

[✓]

[]

[]

