

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Dwelling [no occupant listed]	Frame	Tin	40	20	35	Good	Good	Good	Good	Rebuilt	75

What should be done to make it safe	Remarks
OK	

24 South Battery

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.