

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Mrs. A.B. Williams, dwelling	Frame	slate	60	24	30	*	Down	Badly cracked	Down	Down	\$1500

What should be done to make it safe	Remarks
Rebuild walls and parapet and chimneys	**

25 Legare

* not recorded

** no remarks

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.