

| Owner & Occupant       | Material |      | Dimensions |          |                 | Condition of Walls |       |      |      | Condition of Chimneys or Flues | Damages by Earthquake (\$) |
|------------------------|----------|------|------------|----------|-----------------|--------------------|-------|------|------|--------------------------------|----------------------------|
|                        | Building | Roof | Ft. Long   | Ft. Wide | Ft. High        | North              | South | East | West |                                |                            |
| B.O'Neill,<br>dwelling | Bride    | Tin  | 60         | 25       | not<br>recorded | Anchored           |       |      | →    | Rebuilt                        | none<br>recorded           |

| What should be done to make it safe | Remarks       |
|-------------------------------------|---------------|
| "Now good."                         | none recorded |

38 Chalmers

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.