

HISTORIC CHARLESTON FOUNDATION
HURRICANE EUGO DAMAGE ASSESSMENT FORM

Date of Survey:

CL/LM

Survey Team:

Members:

7-17-90

Video: Reel/Frame

Camera:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: 127 WENTWORTH

Tax Map Number: 457-4-3-35

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐

Attic or Half Story ☒

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐:

Surface Covering: Stucco ☐ Wood Siding ☒ Other ☐:

Roof Covering: Slate ☐ Metal ☒ Tile ☐ Asphalt ☐
Other ☐:

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☐:

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco ☐ Stone ☐ Other ☐

Comments:

HOUSE IN GOOD SHAPE; RE-CONSTRUCTION DONE
BY "PEGASUS GEN. CONSTR." A PERMIT

D25461

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement	[]	☒	[]
1st Floor	☒	[]	[]
2nd Floor	[]	☒ 50%	☒
3rd Floor	[]	[]	[]
4th Floor	[]	[]	[]
Attic	[]	[]	☒ 100%
Doors	☒	[]	[]
Windows	☒	[]	[]
Shutters	☒		
Piazza/Portico	☒	[]	[]
Downspouts	☒	[]	[]
Gutters	[]	[]	☒ look new
Cornice	☒	[]	[]
Parapet	☒	[]	[]
Roof Covering	[]	[]	☒ 100%
Dormers (Number: 3)	☒	[]	[]
Chimneys (Number: 2)	☒	[]	[]

Other Visible Damage

Garden Walls/Fences	[]	[]	[]
Gates	[]	[]	[]
Walkways/Paving	[]	[]	[]
Sidewalks	[]	[]	[]
Trees	[]	[]	[]
Mechanical	[]	[]	[]