

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11/18/89

Survey Team: Rad 2
Members:

Video: Reel/Frame

Camera:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: 15 Thomas

Tax Map Number: 460-16-1-46

Current Owner:

DESCRIPTION

Principal Building Dependency Other

No. of Stories: Basement 1 2 3 4
Attic or Half Story

Material:

Structure: Brick Wood Frame Stone Metal
Other :

Surface Covering: Stucco Wood Siding Other :

Roof Covering: Slate Metal Tile Asphalt
Other :

Piazza: Foundation: Brick Stone Wood
Other :

Main Piazza: Brick Wood Other

Roof Covering (if different from main building): NA

Chimneys: Brick Brick & Stucco Stone Other

Comments: Corner lot hill S, E exposure
major tree damage. This house
is on an elevated foundation so it
did not flood.

Address:

Tax Map No.:

Page 2

Damage Assessment	None	Minor	Major	%
-------------------	------	-------	-------	---

Exterior Features

Walls: Foundation/Basement	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
----------------------------	--------------------------	--------------------------	--------------------------	--

1st Floor	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	210
2nd Floor	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	40

3rd Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
-----------	--------------------------	--------------------------	--------------------------	--

4th Floor	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
-----------	--------------------------	--------------------------	--------------------------	--

Attic	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
-------	-------------------------------------	--------------------------	--------------------------	--

Doors	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
-------	-------------------------------------	--------------------------	--------------------------	--

Windows	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
---------	-------------------------------------	--------------------------	--------------------------	--

			80
--	--	--	----

Shutters

Piazza/Portico	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
----------------	-------------------------------------	--------------------------	--------------------------	--

Downspouts	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
------------	-------------------------------------	--------------------------	--------------------------	--

Gutters	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	90
---------	--------------------------	--------------------------	-------------------------------------	----

Cornice	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	50
---------	--------------------------	-------------------------------------	--------------------------	----

Parapet	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
---------	-------------------------------------	--------------------------	--------------------------	--

Roof Covering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
---------------	-------------------------------------	--------------------------	--------------------------	--

Dormers (Number: 0)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
---------------------	-------------------------------------	--------------------------	--------------------------	--

Chimneys (Number: 0)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
----------------------	-------------------------------------	--------------------------	--------------------------	--

Other Visible Damage

Garden Walls/Fences	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	100
---------------------	--------------------------	--------------------------	-------------------------------------	-----

Gates	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	100
-------	--------------------------	--------------------------	-------------------------------------	-----

Walkways/Paving	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
-----------------	-------------------------------------	--------------------------	--------------------------	--

Sidewalks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
-----------	-------------------------------------	--------------------------	--------------------------	--

Trees	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	80
-------	--------------------------	-------------------------------------	--------------------------	----

Mechanical	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
------------	-------------------------------------	--------------------------	--------------------------	--



Description

Two color slides of 15 Thomas Street (Samuel S. Mills House), taken soon after Hurricane Hugo. Slides are dated October 20, 1989.

a: Thomas Street (front) elevation.

b: Warren Street elevation viewed from the corner of Thomas and Warren Streets.

Part of the Hurricane Hugo Damage Assessment Survey.



Description

Two color slides of 15 Thomas Street (Samuel S. Mills House), taken soon after Hurricane Hugo. Slides are dated October 20, 1989.

a: Thomas Street (front) elevation.

b: Warren Street elevation viewed from the corner of Thomas and Warren Streets.

Part of the Hurricane Hugo Damage Assessment Survey.