

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Mrs. R. L. G. Robinson, Dwelling	Frame	Tin	40	40	35	Good	Good	Good	Good	Broken	225

What should be done to make it safe	Remarks
Rebuild chimneys from roof line and anchor piazza to main building.	

15 THOMAS