

105 East Bay

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
W.C. Miller, Store & Dwelling	Brick	Tile	30	25	35	Division good	Division good	slightly cracked	slightly cracked	Good	150

What should be done to make it safe	Remarks
Attention to east wall	Building in rear uninsurable