

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
J.F. Redding, office & dwelling	Frame	Tin	50	36	24	Good	Good	Good	Good	Rebuilt	[none recorded]

What should be done to make it safe	Remarks
"O.K."	

65 Broad St -

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.