

HISTORIC CHARLESTON FOUNDATION  
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11-28-89

Video: Reel/Frame

Camera:

Slides: [ ]

B.& W.: [ ]

Survey Team:  
Members:

SOB

Name of Property: (if any)

Street Address: 6 ST. MICHAEL'S ALLEY

Tax Map Number: 458-9-3-50

Current Owner:

DESCRIPTION

Principal Building  Dependency [ ] Other [ ]

No. of Stories: Basement [ ] 1 [ ] 2  3 [ ] 4 [ ]

Attic or Half Story

Material:

Structure: Brick  Wood Frame [ ] Stone [ ] Metal [ ]  
Other [ ]:

Surface Covering: Stucco  Wood Siding [ ] Other [ ]:

Roof Covering: Slate [ ] Metal [ ] Tile [ ] Asphalt   
Other [ ]:

Piazza: Foundation: Brick [ ] Stone [ ] Wood [ ]  
Other [ ]:

NA

Main Piazza: Brick [ ] Wood [ ] Other [ ]

Roof Covering (if different from main building):

Chimneys: Brick [ ] Brick & Stucco  Stone [ ] Other [ ]

Comments:

Address:

Tax Map No.:

Page 2

## Damage Assessment

None

Minor

Major

%

## Exterior Features

## Walls: Foundation/Basement

1st Floor

Cracks  
in wall

2nd Floor

3rd Floor

4th Floor

Attic

Doors

Windows

Shutters

Piazza/Portico

NA

Downspouts

Gutters

Cornice

Parapet

Roof Covering

Dormers (Number: NA)

Chimneys (Number: 1)

## Other Visible Damage

Garden Walls/Fences

Gates

Walkways/Paving

Sidewalks

Trees

Mechanical



Hugo Survey photograph

Owner & Occupant	Material		Dimensions			Condition of Walls			
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West
→ Dingle, Dwelling	Brick	slate	30	16	22	Repair + the gable	Good	Good	Good

What should be done to make it  
safe

Remarks

Repair and anchor  
the gable and  
north wall.

6 St. Michael's

[no remarks]

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.