

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
ANDREW SIMONDS, VACANT	BRICK	TILE	50	25	35	DIVISION GOOD	GOOD	BADLY CRACKED BETWEEN OPENINGS	GOOD	MUST BE REBUILT FROM BELOW CEILING & JOISTS	975

What should be done to make it safe	Remarks
ROOF MUST BE REPAIRED; EAST WALL REBUILT; ANCHOR EAST WALL OF KITCHEN	WEST WALL OF KITCHEN MUST COME DOWN

53 East Bay St.

Cite as: *Record of Earthquake Damages*, 1886. On microfiche, Historic Charleston Foundation Archives.