

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Robert Beil, Dwelling	Frame	Tin	36	18	30	G	O	O	D	Rebuilt	

What should be done to make it safe	Remarks
O.K.	1 Legare St.

Cite as: *Record of Earthquake Damages*, 1886. On microfiche, Historic Charleston Foundation Archives.