

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 10/17/89

Video: Reel/Frame

Camera:

Survey Team: SOB #2

Slides: [3.28

Members:

B. & W.: [6.6, 7

Hudgins, March,
Saylor, Reynolds

Name of Property: (if any)

Street Address: 1 Lequire

Tax Map Number: 457-16-3-41

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☒ 1 ☐ 2 ☒ 3 ☐ 4 ☐

Attic or Half Story ☒

Material:

Structure: Brick ☒ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐: foundation

Surface Covering: Stucco ☒ Wood Siding ☒ Other ☐: foundation

Roof Covering: Slate ☐ Metal ☐ Tile ☐ Asphalt ☐
Other ☒: Composite

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☒: Composite

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco ☒ Stone ☐ Other ☐

Comments:

Address: 1 Legare

Tax Map No.: 457-16-3-41

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement

☒☐☐

1st Floor

☒☐☐

2nd Floor

☒☐☐

3rd Floor

☐☐☐

4th Floor

☐☐☐

Attic

☒☐☐

Doors

☒☐☐

Windows

☒☐☐

Shutters

Piazza/Portico

☒☐☐

Downspouts

☒☐☐

Gutters

☒☐☐

Cornice

☒☐☐

Parapet

☒☐☐

Roof Covering

☒☐☐

Dormers (Number: 4)

☒☐☐

Chimneys (Number: 2)

☒☐☐

Other Visible Damage

Garden Walls/Fences

☒☐☐

Gates

☒☐☐

Walkways/Paving

☒☐☐

Sidewalks

☒☐☐

Trees

☐☒☐

Mechanical

☒☐☐

