

231 KING Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
MR. H. LAZARUS, TRUSTEE, STORE & DWELLING	BRICK	TIN	75	20.	35	GOOD	GOOD	SLIGHTLY CRACKED	BADLY CRACKED	NOW GOOD IN MAIN BUILDING	800	REPAIR CRACKED PARTS OF WALLS AND ANCHOR ALL SIDES	REBUILD KITCHEN IN REAR

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives