

9 Pitt

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
E. Blodgett Dwelling	Brick	Tin	30	26	30	Good	Good	Cracked	Cracked	Repaired	[none recorded]

What should be done to make it safe	Remarks
Now being repaired and put in good order.	

Cite as: *Record of Earthquake Damages*, 1886. On microfiche, Historic Charleston Foundation Archives.