

| Owner & Occupant             | Material |      | Dimensions |          |          | Condition of Walls |       |      |      | Condition of Chimneys or Flues | Damages by Earthquake (\$) |
|------------------------------|----------|------|------------|----------|----------|--------------------|-------|------|------|--------------------------------|----------------------------|
|                              | Building | Roof | Ft. Long   | Ft. Wide | Ft. High | North              | South | East | West |                                |                            |
| Governor Aiken,<br>Townhouse | Brick    | Tin  | 80         | 60       | 45       | [not recorded]     |       |      |      | Have been repaired & rebuilt   | 500                        |

| What should be done to make it safe                           | Remarks                     |
|---------------------------------------------------------------|-----------------------------|
| Repair cracked parts of west wall; plastering needs attention | Out buildings in good order |

Gov. Aiken House (Aiken-Rhett House)  
48 Elizabeth St.

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.