

7 Pitt

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
A. W. Lanneau Dwelling	Brick	Tin	60	22	30	Parapet down 5 ft. and rear badly cracked	Good	Cracked over openings	Badly cracked	Must be rebuilt from 2d Story	1250

What should be done to make it safe	Remarks
Anchor east wall from north to south, Rebuild west wall, rebuild north and south parapet wall 5 ft. Repair chimneys.	[none recorded]

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.