

HISTORIC CHARLESTON FOUNDATION  
EMERGENCY HURRICANE DAMAGE ASSESSMENT FORM

Date of Survey: 8/21/90

Survey Team:

Members: RL CL LM

Video: Reel/Frame

Camera:

Slides: [ ]

B&W: [ ]

Name of Property: (if any)

Street Address: 20 Percy St.

Tax Map Number: 460-8-1 - 64

Current Owner:

DESCRIPTION

Principal Building  Dependency [ ] Other [ ]

No. of Stories: Basement [ ] 1 [ ] 2  3 [ ] 4 [ ]  
Attic or Half Story

Material:

Structure: Brick [ ] Wood Frame  Stone [ ] Metal [ ]  
Other [ ]:

Surface Covering: Stucco [ ] ~~Wood~~ Siding  Other [ ]:

Roof Covering: Slate [ ] Metal  Tile [ ] Asphalt [ ]  
Other [ ]:

Piazza: Foundation: Brick  Stone [ ] Wood [ ]  
Other [ ]:

Main Piazza: Brick [ ] Wood  Other [ ]

Roof Covering (if different from main building):

Chimneys: Brick  Brick & Stucco [ ] Stone [ ] Other [ ]

Comments:

Address:

Tax Map No.:

Page 2

## Damage Assessment

None

Minor

Major

s

## Exterior Features

Walls: Foundation/Basement

1st Floor

2nd Floor

3rd Floor

4th Floor

Attic

Doors

Windows

Shutters N/A

Piazza/Portico

Downspouts

Gutters

Cornice N/A

Parapet N/A

Roof Covering

70% damaged

Debris (Number: 3)

Chimneys (Number: 2)

## Other Visible Damage

Garden Walls/Fences N/A

Gates

Walkways/Paving N/A

Sidewalks

Trees

Mechanical



20 Percy Street, August 1990  
Hurricane Hugo Damage Assessment Photo