

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey:

Video: Reel/Frame

Camera:

Slides: []

B. & W.: []

Survey Team:

Members:

Name of Property: (if any)

Street Address: 216 Ashley

Tax Map Number:

Current Owner:

DESCRIPTION

Principal Building Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 [] 3 4 []
Attic or Half Story

Material:

Structure: Brick [] Wood Frame Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding Other []:

Roof Covering: Slate [] Metal [] Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick [] Stone Wood []
Other : CONCRETE

Main Piazza: Brick [] Wood Other []

Roof Covering (if different from main building):

Chimneys: Brick [] Brick & Stucco [] Stone [] Other []

Comments:

Address: 216 Ashley

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement	[X]	[]	[]
1st Floor	[X]	[]	[]
2nd Floor	[X]	[]	[]
3rd Floor	[X]	[]	[]
4th Floor	[]	[]	[]
Attic	[X]	[]	[]
Doors	[X]	[]	[]
Windows	[]	[]	[X]
Shutters			
Piazza/Portico	[X]	[]	[]
Downspouts	[X]	[]	[]
Gutters	[X]	[]	[]
Cornice	[X]	[]	[]
Parapet	[]	[]	[]
Roof Covering	[]	[X]	[]
Dormers (Number:)	[]	[]	[]
Chimneys (Number:)	[]	[]	[]
Other Visible Damage			
Garden Walls/Fences	[X]	[]	[]
Gates	[X]	[]	[]
Walkways/Paving	[X]	[]	[]
Sidewalks	[X]	[]	[]
Trees	[X]	[]	[]
Mechanical	[X]	[]	[]

