

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 7-17-90
Survey Team:
Members: McCallum / LUND

Video: Reel/Frame

Camera:

Slides: []

B. & W.: []

Name of Property: (if any)
Street Address: 7 PITT ST.
Tax Map Number: 457-~~458~~ 3-4-48
Current Owner: F.S. FORESMAN

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐
No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐
Attic or Half Story ☐

Material:

Structure: Brick ☒ Wood Frame ☐ Stone ☐ Metal ☐
Other ☐

Surface Covering: Stucco ☐ Wood Siding ☐ Other ☒: BRICK

Roof Covering: Slate ☐ Metal ☒ Tile ☐ Asphalt ☐
Other ☐: PROBABLY METAL

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☐

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☐ Stone ☐ Other ☐

Comments: BUILDING PERMIT STATES ONLY MINOR
EXTERIOR REPAIRS. # D26157

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

S

Exterior Features

Walls: Foundation/Basement	[]	[X]	[]
1st Floor	[X]	[]	[]
2nd Floor	[X]	[]	[]
3rd Floor	[]	[]	[]
4th Floor	[]	[]	[]
Attic	[]	[]	[]
Doors	[X]	[]	[]
Windows	[X]	[]	[]
Shutters	Ⓚ	X 25%	
Piazza/Portico	[X]	[]	[]
Downspouts	[X]	[]	[]
Gutters	[X]	[]	[]
Cornice	[X]	[]	[]
Parapet	[X]	[]	[]
Roof Covering	[]	[X]	[]
Dormers (Number:)	r/x []	[]	[]
Chimneys (Number: 4)	[X]	[]	[]

Other Visible Damage

Garden Walls/Fences	[]	[]	[]
Gates	[]	[]	[]
Walkways/Paving	[]	[]	[]
Sidewalks	[]	[]	[]
Trees	[]	[]	[]
Mechanical	[]	[]	[]

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 26 July 90

Survey Team:
Members:

CL/CM

Video: Reel/Frame

Camera:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: 7 PITT - REAR #1

Tax Map Number:

Current Owner:

DESCRIPTION

Principal Building [] Dependency ☒ Other []

No. of Stories: Basement [] 1 [] 2 ☒ 3 [] 4 []

Attic or Half Story []

Material:

Structure: Brick ☒ Wood Frame [] Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding [] Other []:

Roof Covering: Slate [] Metal [] Tile [] Asphalt ☒
Other []:

Piazza: Foundation: Brick [] Stone [] Wood []
Other []:

N/A

Main Piazza: Brick [] Wood [] Other []

Roof Covering (if different from main building):

Chimneys: ~~Brick~~ ☒ Brick & Stucco [] Stone [] Other []

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

\$

Exterior Features

Walls: Foundation/Basement

[]

[X]

[]

1st Floor

[]

[X]

[]

2nd Floor

[X]

[]

[]

3rd Floor

[]

[]

[]

4th Floor

[]

[]

[]

Attic

[]

[]

[]

Doors

[X]

[]

[]

Windows

[X]

[]

[]

Shutters

N/A

Piazza/Portico

N/A

[]

[]

[]

Downspouts

[]

[]

[X]

Gutters

[]

[]

[X]

Cornice

[]

[]

[]

Parapet

[X]

[]

[]

Roof Covering

[X]

[]

[]

Dormers (Number: 1/A)

[]

[]

[]

Chimneys (Number: 2)

[]

50%

[X]

Other Visible Damage

Garden Walls/Fences

[]

[]

[]

Gates

[]

[]

[]

Walkways/Paving

[]

[]

[]

Sidewalks

[]

[]

[]

Trees

[]

[]

[]

Mechanical

[]

[]

[]

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 26 JUL 90

Survey Team:
Members:

CU/UM

Video: Reel/Frame

Camera:

Slides: []

E. & W.: []

Name of Property: (if any)

Street Address: 7 PITT REAR #2

Tax Map Number:

Current Owner:

DESCRIPTION

Principal Building [] Dependency ☒ Other []

No. of Stories: Basement [] 1 ☒ 2 [] 3 [] 4 []
Attic or Half Story []

Material:

Structure: Brick ☒ Wood Frame [] Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding [] Other []:

Roof Covering: Slate [] Metal [] Tile [] Asphalt ☒
Other []:

Piazza: Foundation: Brick [] Stone [] Wood []
N/A Other []:

Main Piazza: Brick [] Wood [] Other []

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco [] Stone [] Other []

Comments:

BUILDING NEAR DESTROYED BY WIND/TREE.

RUMORED TO HAVE BEEN USED AS A SCHOOLHOUSE

AT ONE POINT.

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

\$

Exterior Features

Walls: Foundation/Basement

[]

[]

☒

1st Floor

[]

[]

☒70%^{0/6}

2nd Floor

[]

[]

[]

3rd Floor

[]

[]

[]

4th Floor

[]

[]

[]

Attic

[]

[]

[]

Doors

☒

[]

[]

Windows

☒

[]

[]

Shutters

N/A

Piazza/Portico

[]

[]

☒100%^{0/6}

Downspouts

N/A

[]

[]

[]

Gutters

N/A

[]

[]

[]

Cornice

[]

[]

[]

Parapet

[]

☒40%^{0/6}

[]

Roof Covering

☒

[]

[]

Dormers (Number: 1)

[]

[]

[]

Chimneys (Number: 1)

☒

[]

[]

Other Visible Damage

Garden Walls/Fences

[]

[]

[]

Gates

[]

[]

[]

Walkways/Paving

[]

[]

[]

Sidewalks

[]

[]

[]

Trees

[]

[]

[]

Mechanical

[]

[]

[]

