

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
8 Bee Street, J. Meyers, Dwelling	Frame	Tin	40	16	23	G	O	O	D	Good	N/A

What should be done to make it safe	Remarks
O.K.	

Cite as: *Record of Earthquake Damages*, 1886. On microfiche, Historic Charleston Foundation Archives.

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 3 AUG 1990

Survey Team:

Members: CLKM / NR

Videos: Reel/Frame

Camera:

Slides: [] [] [] []
E.S.W.: [] [] [] []

Name of Property: (if any) 8 BEE ST.

Street Address:

Tax Map Number: 460-15-2-92

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐
Attic or Half Story ☒

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐

Surface Covering: Stucco ☐ Wood Siding ☒ Other ☐

Roof Covering: Slate ☐ Metal ☒ Tile ☐ Asphalt ☐
Other ☐

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☐

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☒ Stone ☐ Other ☐

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

\$

Exterior Features

Walls: Foundation/Basement

☒☐☐

1st Floor

☐☐☒

2nd Floor

☐☐☒

3rd Floor

☐☐☐

4th Floor

☐☐☐

Attic

☐☐☒

Doors

☒☐☐

Windows

☒☐☐

Shutters

☒ 20%

Piazza/Portico

☒☐☐

Downspouts

☐☒☐

Gutters

☐☐☒ 100%

Cornice

☒☐☐

Parapet

☐☐☐

Roof Covering

☐☐☒ 100%

Dormers (Number: 0)

☐☐☐

Chimneys (Number: 1)

☒☐☐

Other Visible Damage

Garden Walls/Fences

☐☐☐

Gates

☐☐☐

Walkways/Paving

☐☐☐

Sidewalks

☐☐☐

Trees

☐☐☐

Mechanical

☐☐☐

