

28 CHAPEL

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Mrs. A. Vanderhorst, dwelling	Brick	Slate	40	25	40	Good	Good	Good	Good	Have been put in good order	*

What should be done to make it safe	Remarks
*	Brick kitchen in rear in good order

* nothing recorded