

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 13 AUGUST 1990

Video: Reel/Frame

Survey Team:

Camera:

Slides: [/]

E. & W.: [(]

Members: LM/NR/CL

Name of Property: (if any)

Street Address: 1 KRACKE

Tax Map Number: 460-11-2-76

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☒ 1 ☐ 2 ☐ 3 ☐ 4 ☐

Attic or Half Story ☒

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐:

Surface Covering: Stucco ☐ Wood Siding ☒ Other ☐:

Roof Covering: Slate ☐ Metal ☒ Tile ☐ Asphalt ☐
Other ☐:

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☐:

Main Piazza: Brick ☐ Wood ☒ Other ☐

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☐ Stone ☐ Other ☐

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

5

Exterior Features

Walls: Foundation/Basement

☒☐☐

1st Floor

☒☐☐

2nd Floor

☐☐☐

3rd Floor

☐☐☐

4th Floor

☐☐☐

Attic

☐☒☐

Doors

☒☐☐

Windows

☐☒☐

Shutters

☒

Piazza/Portico

☒☐☐

Downspouts

☒☐☐

Gutters

☒☐☐

Cornice

☐☐☐

Parapet

☒☐☐

Roof Covering

☐☒☐

Dormers (Number: 0)

☐☐☐

Chimneys (Number: 0)

☐☐☐

Other Visible Damage

Garden Walls/Fences

☐☐☐

Gates

☐☐☐

Walkways/Paving

☐☐☐

Sidewalks

☐☐☐

Trees

☐☐☐

Mechanical

☐☐☐

