

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Masonic Fraternity Hall	Brick	Tin	100	60	60	Good	Good	Good	cracked over openings	Good	\$ 500

What should be done to make it safe	Remarks
"Now good."	[none recorded]

270 King "Masonic Fraternity Hall"