

328 KING

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
SISTERS OF MERCY - STORE & DWELLING	Brick	SLATE	90	30	40	MAIN BUILDING CRACKED	DIVISION GOOD	SHOULD COME DOWN	BADLY CRACKED	DOWN	\$ 2000

What should be done to make it safe	Remarks
Rebuild east wall & kitchen wing from ground, Rebuild chimneys from below ceiling joists, where down; north wall of kitchen wing good part of the way; repair all plastering.	Rebuild west wall between openings, and anchor wall.

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.