

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Miss H. Vennings, Dwelling	Frame	Shingle	40	18	22	G	O	O	D	Repaired	40

What should be done to make it safe	Remarks

47 Chapel

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey:

Video: Reel/Frame

Survey Team:

Camera:

Members:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: 47 Chapel

Tax Map Number: 459-13-1 #73

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 ☒ 3 [] 4 []

Attic or Half Story []

Material:

Structure: Brick [] Wood Frame ☒ Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding ☒ Other []:

Roof Covering: Slate [] Metal ☒ Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick ☒ Stone [] Wood []
Other []:

Main Piazza: Brick [] Wood ☒ Other []

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco [] Stone [] Other []

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement	☒	☐	☐
1st Floor	☐	☒	☐
2nd Floor	☐	☒	☐
3rd Floor	☐	☒	☐
4th Floor	☒	☐	☐
Attic	☒	☐	☐
Doors	☒	☐	☐
Windows	☐	☐	☒
Shutters			
Piazza/Portico	☐	☒	☐
Downspouts	☐	☒	☐
Gutters	☐	☒	☐
Cornice	☒	☐	☐
Parapet	☒	☐	☐
Roof Covering	☐	☐	☒
Dormers (Number:)	☒	☐	☐
Chimneys (Number: 2)	☒	☐	☐

Other Visible Damage

Garden Walls/Fences	☒	☐	☒
Gates	☐	☐	☒
Walkways/Paving	☒	☐	☐
Sidewalks	☒	☐	☐
Trees	☐	☐	☒
Mechanical	☒	☐	☐

