

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Myer Stern, Store & Dwelling	Brick	Tile	130	25	35	Good	Good	slightly cracked over openings	Now being rebuilt	Good	800

What should be done to make it safe	Remarks
Now being repaired and anchored	

330 King

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Myer Stern, Vacant	Brick	Slate	—	—	—	Good	Good	Good	Good	Good	400

What should be done to make it safe	Remarks
Repairs now going on; OK	

332 King

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives.