

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11.28.89

Video: Reel/Frame

Camera:

Survey Team:

Slides: []

Members:

B. & W.: []

Name of Property: (if any)

Street Address:

Tax Map Number:

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☐ 3 ☒ 4 ☐

Attic or Half Story ☒

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐
Other []:

Surface Covering: Stucco ☐ Wood Siding ☒ Other []:

Roof Covering: Slate ☒ Metal ☐ Tile ☐ Asphalt ☐
Other []:

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other []:

Main Piazza: Brick ☐ Wood ☒ Other []

Roof Covering (if different from main building):

Chimneys: Brick ☐ Brick & Stucco ☒ Stone ☐ Other []

Comments:

Shutters are missing
in process of restoring house

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement

[]

[]

[]

1st Floor

[]

[]

[]

2nd Floor

[]

[]

[]

3rd Floor

[]

[]

[]

4th Floor

[]

[]

[]

Attic

[]

[]

[]

Doors

[X]

[]

[]

Windows

[]

[]

[]

Shutters

Piazza/Portico

[]

[X]

[]

Downspouts

[X]

[]

[]

Gutters

[]

[]

[]

Cornice

[X]

[]

[]

Parapet

NA

[]

[]

[]

Roof Covering

[]

[]

[]

Dormers (Number: 3)

[]

[X]

[]

Chimneys (Number:)

[]

[]

[]

Other Visible Damage

Garden Walls/Fences

[X]

[]

[]

Gates

[X]

[]

[]

Walkways/Paving

[X]

[]

[]

Sidewalks

[X]

[]

[]

Trees

[X]

[]

[]

Mechanical

[]

[]

[]

H₂O damageH₂OH₂O

45%

20% ballistics are missing

100%

25% (+) window
40% window
+ one
sash-gone