

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 12/15/89 (4/18/91) Video: Reel/Frame

Survey Team: LVM (NELSON) Camera:
Members: Slides: []
B. & W.: [4A]

Name of Property: (if any)

Street Address: 19 1/2 LINE ST.

Tax Map Number: 459-5-3-182 145

Current Owner:

DESCRIPTION :

Principal Building Dependency Other

No. of Stories: Basement 1 2 3 4
Attic or Half Story

Material:

Structure: Brick Wood Frame Stone Metal
Other :

Surface Covering: Stucco Wood Siding Other :

Roof Covering: Slate Metal Tile Asphalt
Other :

Piazza: Foundation: Brick Stone Wood
Other :

Main Piazza: Brick Wood Other

Roof Covering (if different from main building):

Chimneys: Brick Brick & Stucco Stone Other

Comments:

Address: 19 1/2 LINE ST. Tax Map No.: 459-5-3-145 Page 2

Damage Assessment None Minor Major %

Exterior Features

| | | | |
|----------------------------|-----|-----|-----|
| Walls: Foundation/Basement | [X] | [] | [] |
| 1st Floor | [X] | [] | [] |
| 2nd Floor | [] | [] | [] |
| 3rd Floor | [] | [] | [] |
| 4th Floor | [] | [] | [] |
| Attic | [X] | [] | [] |
| Doors | [X] | [] | [] |
| Windows | [X] | [] | [] |
| Shutters | | | |
| Piazza/Portico | [] | [] | [] |
| Downspouts | [X] | [] | [] |
| Gutters | [X] | [] | [] |
| Cornice | [] | [] | [] |
| Parapet | [] | [] | [] |
| Roof Covering | [] | [X] | [] |
| Dormers (Number:) | [] | [] | [] |
| Chimneys (Number:) | [] | [] | [] |

Other Visible Damage

| | | | |
|---------------------|-----|-----|-----|
| Garden Walls/Fences | [] | [] | [] |
| Gates | [] | [] | [] |
| Walkways/Paving | [] | [] | [] |
| Sidewalks | [] | [] | [] |
| Trees | [] | [] | [] |
| Mechanical | [] | [] | [] |

