

**Freedman's Cottage Survey**

**19.5 Line Street**

Walls/construction: frame construction, Simple drop siding

Porch: halfway enclosed

Piazza screen: none now, although some evidence of beaded flushboard siding

Gable: minimal gable details and overhang

Windows: addition at front obscures original windows

Openings into main house: entry into first room visible

Foundation: Brick, stuccoed

Chimney: No chimney

Note: Vacant and boarded. Addition at front covers original windows, and house is greatly altered.  
[above house also in Eastside survey]

