

436-438 KING

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Jno. Feehan — store	BRICK	TIN	50	40	23	BADLY CRACKED	VERY BAD	BADLY CRACKED	BADLY CRACKED	VERY BAD; NEED PROMPT ATTENTION	\$1500

What should be done to make it safe	Remarks
SHOULD BE THOROUGHLY REPAIRED; IN VERY BAD CONDITION,	No. 436 BAD WRECK; TOP STORY MUST COME DOWN; KITCHEN IN REAR NOT INSURABLE.

Cite as: *Record of Earthquake Damages*, 1886. On microfiche, Historic Charleston Foundation Archives.

1886 Earthquake Damage Assessment - appears to be two buildings assessed at the same time, 436 getting the worst of it