

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	\$ Damages by Earthquake
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Wm. Parker, The Shop & Dwelling	Brick	Tin	40	24	35	Good	Good	Good	Good	Good-rebuilt	\$250

What should be done to make it safe	Remarks
Has been put in good repair	[none recorded]

12 Tradd St.