

Owner & Occupant	Material		Dimensions		Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
G. Dreyer, dwelling	Brick	Tile	38	18	[Not recorded]	Good	Good	Good	Good	Good	Good
What should be done to make it safe	Remarks										
	* *										
	35 Tread										
	* nothing recorded for these fields										

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.