

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
Mrs. R. Murphy, Saloon	Brick	Tin	75	25	35	Good	Slightly cracked & over openings	Slightly cracked between openings	Badly cracked at corner	Top off. 1 cracked between stories in front	1700

What should be done to make it safe	Remarks
Cracks in east & west walls repaired & well anchored. Chimneys require prompt attention.	Chimney in 2nd story room should come down.

89 East Bay St.

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.