

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
Mrs. Cart, Dwelling 14 Gadsden	Frame	Slate	50	30	30	Good			→	Have been rebuilt	[None recorded]	[nothing recorded]	Kitchen adjoining has old shingled roof.

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives