

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)	What should be done to make it safe	Remarks
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West				
Estate D. Loeb, dwelling	Brick	Slate	50	16	24	Good	Good	Good	Good	Tops down	\$75	Rebuild chimney tops from roof	

Cite as: Record of Earthquake Damages, 1886. On microfiche, Historic Charleston Foundation Archives

63 Anson [was 61 Anson in 1886]