

Owner & Occupant	Material		Dimensions			Condition of Walls			Condition of Chimneys or Flues	Damages by Earthquake (\$)	
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
H. E. Young, dwelling	Frame	slate	40	30	24	Good	Good	Good	Good	Have been rebuilt	[None assessed]

What should be done to make it  
safe

Remarks

"O.K."  
[no remarks]

22 Legare

Cite as: *Record of Earthquake Damages, 1886*. On microfiche. Historic Charleston Foundation Archives.