

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
17 Chalmers, Mrs. C. Garety, Dwelling	Brick	Tile	15	18	25	C R A C K E D				Down	\$425

What should be done to make it safe	Remarks
Rebuild north & south walls between windows & doors; rebuild east & west parapets; repair roof; repair chimneys from 2nd story	

Cite as: *Record of Earthquake Damages, 1886*. On microfiche, Historic Charleston Foundation Archives.