

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey:

Video: Reel/Frame

Survey Team:

Camera:

Members:

Slides: []

B. & W.: []

Name of Property: (if any) *Mrs Robinson Outbuilding*

Street Address: *63 Anson*

Tax Map Number: *45-8-1-3 -11*

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 ☒ 3 [] 4 []
Attic or Half Story []

Material:

Structure: Brick ☒ Wood Frame [] Stone [] Metal []
Other []:

Surface Covering: Stucco ☒ Wood Siding [] Other []:

Roof Covering: Slate [] Metal ☒ Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick [] Stone [] Wood []
Other []:

Main Piazza: Brick [] Wood [] Other []

Roof Covering (if different from main building):

Chimneys: Brick ☒ Brick & Stucco [] Stone [] Other []

Comments: *basement property -*

Address: 603 ANSON

Tax Map No.: 458-1-3-11

Page 2

Damage Assessment

None

Minor

Major

8

Exterior Features

Walls: Foundation/Basement	[]	[✓]	[] 1st story
1st Floor	[]	[✓]	[]
2nd Floor	[]	[✓]	[]
3rd Floor	[✓]	[]	[]
4th Floor	[✓]	[]	[]
Attic	[✓]	[]	[]
Doors	[✓]	[]	[]
Windows	[✓]	[]	[]
Shutters			
Piazza/Portico	NA []	[]	[]
Downspouts	[]	[✓]	[] 25%
Gutters	[]	[]	[✓ 100%
Cornice	[]	[✓]	[]
Parapet	[✓]	[]	[]
Roof Covering	[]	[]	[]
Dormers (Number:)	[]	[]	[]
Chimneys (Number:)	[]	[]	[]

Other Visible Damage

Garden Walls/Fences	[]	[]	[]
Gates	[]	[]	[]
Walkways/Paving	[]	[]	[]
Sidewalks	[]	[]	[]
Trees	[]	[]	[]
Mechanical	[]	[]	[]

