

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 11/29/89

Survey Team:
Members: SOB

Video: Reel/Frame

Camera:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: 22 Legre

Tax Map Number: 457-16-1-68

Current Owner:

DESCRIPTION

Principal Building ☒ Dependency ☐ Other ☐

No. of Stories: Basement ☐ 1 ☐ 2 ☒ 3 ☐ 4 ☐

Attic or Half Story ☐

Material:

Structure: Brick ☐ Wood Frame ☒ Stone ☐ Metal ☐
Other ☐:

Surface Covering: Stucco ☐ Wood Siding ☒ Other ☐:

Roof Covering: Slate ☒ Metal ☐ Tile ☐ Asphalt ☐
Other ☐:

Piazza: Foundation: Brick ☒ Stone ☐ Wood ☐
Other ☐:

Main Piazza: Brick ☐ Wood ☒ Other ☐:

Roof Covering (if different from main building): metal

Chimneys: Brick ☒ Brick & Stucco ☐ Stone ☐ Other ☐

Comments: South dormer torn up badly.

West chimney sheared at ridge line.

Very severely damaged.

Address:

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement

/

[]

[]

1st Floor

/

[]

[]

2nd Floor

/

[]

[]

3rd Floor

[]

[]

[]

4th Floor

[]

[]

[]

Attic

/

[]

[]

Doors

/

[]

[]

Windows

[]

/

[]

20

Shutters

/

Piazza/Portico

/

[]

[]

Downspouts

[]

/

[]

20

Gutters

[]

/

[]

50

Cornice

/

[]

[]

Parapet

/

[]

[]

Roof Covering

[]

[]

/

80

Dormers (Number: 3)

[]

/

[]

50

Chimneys (Number: 2)

[]

[]

/

100

Other Visible Damage

Garden Walls/Fences

/

[]

[]

Gates

/

[]

[]

Walkways/Paving

/

[]

[]

Sidewalks

/

[]

[]

Trees

/

[]

[]

Mechanical

/

[]

[]