

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
R. Arnold, Dwelling	Brick & Frame	Slate	50	40	35	Good	Good	Good	Good	Have been rebuilt	\$350

What should be done to make it safe	Remarks
Repair plastering & cracks in foundation	

34 Chapel St.

Cite as: *Record of Earthquake Damages*, 1886. On microfiche, Historic Charleston Foundation Archives.

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey:

Video: Reel/Frame

Camera:

Survey Team:

Slides: []

Members:

B. & W.: []

Name of Property: (if any)

Street Address: 34 Chapel

Tax Map Number: 459-13-1-58

Current Owner:

DESCRIPTION

Principal Building Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 [] 3 4 []
Attic or Half Story []

Material:

Structure: Brick [] Wood Frame Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood Siding Other []:

Roof Covering: ^{Super} Slate Metal [] Tile [] Asphalt []
Other []:

Piazza: Foundation: Brick Stone [] Wood []
Other :

Main Piazza: Brick [] Wood Other []

Roof Covering (if different from main building):

Chimneys: Brick [] Brick & Stucco Stone [] Other []

Comments:

Address: 34 Chapel

Tax Map No.:

Page 2

Damage Assessment

None

Minor

Major

%

Exterior Features

Walls: Foundation/Basement

1st Floor

2nd Floor

3rd Floor

4th Floor

Attic

Doors

Windows

Shutters

few

Piazza/Portico

Downspouts

Gutters

Cornice

Parapet

Roof Covering

Dormers (Number: 0)

Chimneys (Number: 2)

Other Visible Damage

Garden Walls/Fences

Gates

Walkways/Paving

Sidewalks

Trees

Mechanical

HISTORIC CHARLESTON FOUNDATION
HURRICANE HUGO DAMAGE ASSESSMENT FORM

Date of Survey: 6/28/90

Survey Team: Kerley Lund
Members: Rowe McCullum

Video: Reel/Frame

Camera:

Slides: []

B. & W.: []

Name of Property: (if any)

Street Address: 34 Chapel

Tax Map Number: 459-13-1 lot 58

Current Owner:

DESCRIPTION

Principal Building Dependency [] Other []

No. of Stories: Basement [] 1 [] 2 3 [] 4 []

Attic or Half Story

Material:

Structure: Brick [] Wood Frame Stone [] Metal []
Other []:

Surface Covering: Stucco [] Wood siding Other []:

Roof Covering: Slate [] Metal [] Tile [] Asphalt []

Other : *Asbestos Shingles*

Piazza: Foundation: Brick Stone [] Wood []
Other []:

Main Piazza: Brick [] Wood Other []

Roof Covering (if different from main building):

Chimneys: Brick Brick & Stucco [] Stone [] Other []

Comments:

Address:

Tax Map No.:

Page 2

Damage Assessment None Minor Major \$

Exterior Features

Walls: Foundation/Basement	[X]	[]	[]
1st Floor	[X]	[]	[]
2nd Floor	[X]	[]	[]
3rd Floor	[X]	[]	[]
4th Floor	[X]	[]	[]
Attic	[X]	[]	[]
Doors	[X]	[]	[]
Windows	[X]	[]	[]

Shutters

Piazza/Portico	[X]	[]	[]
Downspouts	[X]	[]	[]
Gutters	[X]	[]	[]
Cornice	[X]	[]	[]
Parapet	[X]	[]	[]
Roof Covering	[X]	[]	[]
Dormers (Number: 1)	[]	[]	[]
Chimneys (Number: 2)	[]	[]	[]

Other Visible Damage

Garden Walls/Fences	[]	[]	[]
Gates	[]	[]	[]
Walkways/Paving	[]	[]	[]
Sidewalks	[]	[]	[]
Trees	[]	[]	[]
Mechanical	[]	[]	[]

N/A