

Owner & Occupant	Material		Dimensions			Condition of Walls				Condition of Chimneys or Flues	Damages by Earthquake (\$)
	Building	Roof	Ft. Long	Ft. Wide	Ft. High	North	South	East	West		
H. Dessbrock, Store & Dwelling	Brick	Tin	40	25	25	Badly cracked	Cracked near openings	Good	Good	Good	\$150

What should be done to make it safe	Remarks
Repair east wall over openings and anchor from north to south walls; repair plastering and large crack in north wall.	[none recorded]

39 King St.